

JOB SUMMARY



Job No. | 19425045
Date | 8/24/2020
Type | Cleaning
PO No. |

From | **Southern Outdoor Restoration**
3217 Northside Drive
Raleigh, NC 27615
(919) 366-7474

Job For | **Omega Association Management, Inc.**
Creeks at Weston
Suttons Walk Drive
Cary, NC 27513

Services

August

- Jet all pop-ups. Mark with green flag where the exit is once its cleared. Mark with a red flag if we cannot eliminate the clog
- Use hydrant meter for water access
- Phillip to use a drone to photograph every building and document where the pop-up drains are located. Hand over a physical copy of all the building maps as well as a link to all of these in Dropbox as an electronic version.


Parts, labor and items used

		QTY
Service	Custom Gutter-Related Project	1
Service	Hydrant Meter Rental and Use	1

Files and Photos







Deficiencies

NEW
Deficient
DISCOVERED
09/01/2020
10:39 AM

Description:

455 Talons rest way - pop up drain broken and missing cap



Comments

No Comments